

**VILLAGE OF ANTIOCH, ILLINOIS  
ROUTE 83 & DOWNTOWN CORRIDOR STUDY**

**HISTORIC SURVEY**



**SURVEY FORMS:  
DOWNTOWN DISTRICT  
& SELECTED PROPERTIES**



**GRANACKI**  
HISTORIC CONSULTANTS

2006



# DOWNTOWN DISTRICT





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - professional"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade - financial institution"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="Imposing Temple Front building with classical detailing."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Temple Front"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text" value="Classical"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1926"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="'Antioch Illinois, Revisited'"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Stone"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="metal"/>
WALL MATERIAL (original)	<input type="text" value="Stone"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="casement; fixed"/>
		WINDOW CONFIG	<input type="text" value="grouped; 1 light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	First National Bank of Antioch
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

**HISTORIC  
INFO**

Bank was constructed on site of the former Old Opera House ("Antioch Illinois, Revisited," p. 16).

**LANDSCAPE**

On southwest corner of Lake and Main; hold prominent corner at major intersection of downtown Antioch; mostly commercial uses on blocks; busy highway along east façade; building built to sidewalk and lot lines

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\lake0360.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Recreation and Culture - theater"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Recreation and Culture - theater"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block/Theater"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1920"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="metal"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="plate glass"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/display"/>
		WINDOW CONFIG	<input type="text"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Storefront and theater entry has been reconfigured with non-historic materials including wood verticals, aluminum doors, plate glass display windows and cedar shake canopy over entire storefront and projects over theater entry

**HISTORIC INFORMATION**

HISTORIC NAME	Antioch Theater
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on south side of Lake Street with commercial uses on the block; front sidewalks; building constructed to lot lines and sidewalks

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	images\lake0374-378.jpg

**DIGITAL PHOTO ID2**



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="fair"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1890"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="plate glass"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixed"/>
		WINDOW CONFIG	<input type="text" value="2/2; display"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Entire storefront has been replaced with non-historic materials (1950s) including artificial stone cladding, large plate glass display windows, and aluminum door and transom; replacement 2nd floor entry door

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Johnson Jewelers of Antioch
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on north side of Lake Street between Main and Toft; commercial uses on the block; asphalt drive and alley to west; building angled on lot; tree at front; large front sidewalks

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\lake038 1.jpg

**DIGITAL PHOTO ID2**



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	Cantar & DeMartin Law Offices
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on south side of Lake Street with commercial uses on the block; front sidewalks; building constructed to lot lines and sidewalks; gap between buildings on west façade

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	\\images\lake038 2.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - restaurant"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="One Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1950s"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text" value="1970s"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Stucco"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Concrete - block"/>	WINDOW MATERIAL	<input type="text" value="metal"/>
WALL MATERIAL (original)	<input type="text" value="Concrete - block"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Unknown"/>	WINDOW TYPE	<input type="text" value="casement"/>
		WINDOW CONFIG	<input type="text" value="multilight"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Cedar shake canopy over entire storefront; stucco cladding; all metal replacement windows and doors with multilight configuration

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Oliverii North Pizzeria
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on south side of Lake Street with commercial uses on the block; front sidewalks; building constructed to lot lines and sidewalks; gap between buildings on east façade

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\lake0384.jpg

DIGITAL PHOTO ID2



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business; Domestic - multiple dwe"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade - business; Domestic - multiple dwe"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="not altered"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Freestanding Commercial"/>	PLAN	<input type="text" value="irregular"/>
DETAILS	<input type="text" value="Mansard"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1970s"/>	ROOF TYPE	<input type="text" value="Mansard"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="2nd floor"/>
WALL MATERIAL 2 (current)	<input type="text" value="Wood - vertical board; aluminum"/>	WINDOW MATERIAL	<input type="text" value="metal"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Wood - vertical board"/>	WINDOW TYPE	<input type="text" value="double hung/fixed/sliding"/>
		WINDOW CONFIG	<input type="text" value="display; 1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Backlit canopy over east storefront covering 2nd floor balcony; replacement aluminum door on east storefront

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	The Mexican Paradise Café
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

Other businesses (2005): Cigarette Depot and ForbiddenButterfly.com

**LANDSCAPE**

Midblock on north side of Lake Street between Main and Toft; commercial uses on block; tree at front; building angled on lot; large front sidewalk area with café seating; asphalt drive and parking to east; built to lot lines

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\lake038 9-391.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="Minor alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="One Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1900"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text" value="c. 1920"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Wood - vertical board"/>	WINDOW MATERIAL	<input type="text" value="Copper"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="display"/>
		WINDOW CONFIG	<input type="text" value="Single light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Brick on east storefront bulkhead has been painted; some windows replaced; vertical wood siding above storefronts on both sides

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Antioch Farmers Insurance
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

Building was a garage in 1915; by 1924, it had been converted to 2 storefronts (Sanborn Maps from 1915,1924)

**LANDSCAPE**

Northeast corner of Victoria and Lake; storefronts are raised above grade, with a raised sidewalk and a set of two concrete steps leading up to the entries

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\lake0390-392.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Multiple storefronts added with aluminum entries and metal display windows; canvas awnings over entries

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Law Offices/Martial Arts/Curves
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

At northeast corner of Lake and Toft Avenue; asphalt parking lot with curb cuts actually at corner and building to east; front sidewalks; commercial uses along Lake and mixed uses along Toft; building built to front sidewalk and east lot line; some trees

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\lake039 5-397.jpg

DIGITAL PHOTO ID2	
-------------------	--

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade - business"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="Minor alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="One Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1940"/>	ROOF TYPE	<input type="text" value="Flat/Mansard"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible/Wood - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Parged/NV"/>
WALL MATERIAL (current)	<input type="text" value="Stone/Stucco"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Aluminum"/>
WALL MATERIAL (original)	<input type="text" value="Stone/Stucco"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Brick"/>	WINDOW TYPE	<input type="text" value="display"/>
		WINDOW CONFIG	<input type="text" value="Single light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Southwest corner of Victoria and Lake; front and east sidewalks; mature trees

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\lake0398-410.jpg"/>

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text" value="GRANACKI HISTORIC CONSULTANTS"/>
SURVEYDATE	<input type="text" value="11/2/2005"/>
SURVEYAREA	<input type="text" value="DOWNTOWN ANTIOCH"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade - business"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="One Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1950s"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Wood - vertical board"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Unknown"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Brick"/>	WINDOW TYPE	<input type="text" value="display"/>
		WINDOW CONFIG	<input type="text" value="single-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Replacement windows; replacement doors in downsized openings; vertical wood siding; tile bulkhead

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Jack's Four Squires
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on south side of commercial street; front sidewalk; parking lot/strip mall to west; east party wall; mature trees to front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\lake0414.jpg

DIGITAL PHOTO ID2



**SURVEY INFORMATION**

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Government - village hall"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="Major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="No style"/>	PLAN	<input type="text" value="irregular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1952"/>	ROOF TYPE	<input type="text" value="Flat/Hipped"/>
OTHER YEAR	<input type="text" value="1963"/>	ROOF MATERIAL	<input type="text" value="Not visible/Standing metal se"/>
DATESOURCE	<input type="text" value="Knirsch/Chicago Tribune"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Stone"/>	WINDOW MATERIAL	<input type="text" value="Metal"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Glass Brick"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="fixed"/>
		WINDOW CONFIG	<input type="text" value="Single light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Corner storefront on northernmost section filled in with stone veneer

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Antioch Village Hall
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

According to "The Town of Antioch: Its First Hundred Years," part of current Village Hall originally constructed in 1952 to house Fire Department's equipment and trucks (37); CHICAGO TRIBUNE article from 9/12/1963 about new village hall at Orchard & Main

**LANDSCAPE**

northwest corner of Orchard Street and Main Street; front and south sidewalks; front lawn with concrete walkways and stone memorial; mature trees

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0874.jpg

DIGITAL PHOTO ID2

\\images\main0882.jpg

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

**ANTIOCH LETS CONTRACT FOR VILLAGE HALL**

*Chicago Tribune (1963-Current file); Sep 12, 1963; ProQuest Historical Newspapers Chicago Tribune (1849 - 1985)*  
pg. N9

# **ANTIOCH LETS CONTRACT FOR VILLAGE HALL**

## **Completion Expected Within 4 Months**

A contract for \$21,952 has been awarded to Vos Construction company, 523 Windsor st., Antioch, for construction of a new Antioch village hall to be located at Main and Orchard streets, according to Clarence B. Shultis, village clerk.

Construction already is under way, Shultis said, and plans now call for the building to be completed in four months.

Included in the building to be located next to the village fire station, will be the mayor's and clerk's offices, a conference room, and space for filing and storage.

The police department will occupy all of the present village hall as soon as the new one is completed, Shultis said. At present, the department occupies a small room in the rear of the building. The present village hall, 875 Main st., was built about 50 years ago.

Architect for the new hall is Elmer A. Anderson of Glenview.





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Government - city hall/fire station"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="Historically significant as one of a number sites that housed the Village Hall and Fire Station."/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="One Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1916"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="Antioch: A Pictorial History"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="plate"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="display"/>
		WINDOW CONFIG	<input type="text"/>

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**STOREFRONT FEATURES**




**STOREFRONT ALTERATIONS**

Storefront is a historic alteration from late 1940s or early 1950s with historic materials

**HISTORIC INFORMATION**

HISTORIC NAME	Antioch Village Hall and Fire Station
COMMON NAME	
COST	
ARCHITECT	Sibley, Nason E.
ARCHITECT2	
BUILDER	Dupree, John
ARCHITECT SOURCE	



**HISTORIC INFO**

Stone panel at center reads "Village Hall and Fire Station"; side panels read "W. S. Rinear, president. Nason E. Sibley, architect, John Dupree, contractor." See continuation sheet for more historic information.

**LANDSCAPE**

Almost at northeast corner of Orchard St and Main Street, grassy lawn with landscaping to north; brick paver sidewalks; buildings constructed to sidewalks; street trees and lighting

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0875.jpg

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 875

STREET Main

## ADDITIONAL PHOTOS OR INFORMATION

### *Historic Information*

Historic photograph of the building is on page 125 of *Antioch, Illinois: A Pictorial History*. An excerpt from the *Antioch News* accompanies the picture:

“Antioch is to have a village hall. . . . Work will be rushed. The building which is to be of brick will be a one story structure 22 feet in width and 60 feet in length. The front room 22 x 36 will be given over to the use of the fire department, while the room in the rear will be for the use of the Village Board. . .” (November 16, 1916)





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Recreation and Culture - theater"/>
CONDITION	<input type="text" value="fair"/>	HISTORIC FUNCTION	<input type="text" value="Recreation and Culture - theater"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Historically significant, but lacking in architectural integrity."/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1915"/>	ROOF TYPE	<input type="text" value="Parapet"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Concrete - block"/>	WINDOW MATERIAL	<input type="text" value="metal"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="fixed; casement"/>
		WINDOW CONFIG	<input type="text"/>

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**STOREFRONT FEATURES**




**STOREFRONT ALTERATIONS**

Entire storefront has been reconfigured and refaced with artificial stone; aluminum doors; replacement marquee

**HISTORIC INFORMATION**

HISTORIC NAME	Crystal Theater
COMMON NAME	P.M. & L. Theater
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

Historic photograph of building located on page 125 of ANTIOCH, ILLINOIS: A PICTORIAL HISTORY.

**LANDSCAPE**

Midblock on east side of commercial highway between Orchard and Lake; building constructed to sidewalk and south lot line; front sidewalks

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0877.jpg

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Cedar shake awning across entire front of building; artificial stone cladding over bulkhead and central pier dividing storefronts

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	SuzAnne's Picture Framing/SomethingSweet
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; walkway in between buildings to south

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0879-881.jpg

<b>DIGITAL PHOTO ID2</b>	
--------------------------	--

**SURVEY INFORMATION**

<b>PREPARER</b>	JENNIFER KENNY
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Community Building"/>
CONDITION	<input type="text" value="Good/Fair"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade - business"/>
INTEGRITY	<input type="text" value="Major alterations"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="Major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1892"/>	ROOF TYPE	<input type="text" value="Truss"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="Plaque"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Stone veneer"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Aluminum"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="sliding/Double hung"/>
		WINDOW CONFIG	<input type="text" value="3-part; 1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Storefront level covered with stone veneer; what may have been display windows have been bricked in (not sure if the stone veneer pilasters that are now on the storefront are indications of some original configuration; 1st floor entrance at south end

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Antioch Community Center
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	




**HISTORIC INFO**



**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; light post in front of building; no trees



**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0884.jpg

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - restaurant"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1903"/>	ROOF TYPE	<input type="text" value="Parapet"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="date plate"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Common brick"/>	WINDOW MATERIAL	<input type="text" value="infilled"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Common brick"/>	WINDOW TYPE	<input type="text"/>
		WINDOW CONFIG	<input type="text"/>

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**STOREFRONT FEATURES**




**STOREFRONT ALTERATIONS**

Entire storefront has been reconfigured with non-historic materials including stacked insul brick, recessed entries to storefront and second floor that is up two stairs

**HISTORIC INFORMATION**

HISTORIC NAME	Union Block
COMMON NAME	Binanti's Taste of Italy II
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

Masonic lodge on 2nd floor (2005)

**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; walkway to north between buildings; building constructed to front sidewalk and lot lines; similar in character and materials to building to south

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0885.jpg

DIGITAL PHOTO ID2	
-------------------	--

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1903"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="date block"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Storefronts and second floor entries have been reconfigured with mostly non-historic replacement materials including wood vertical board cladding, plate glass display windows, and aluminum entry doors

**HISTORIC INFORMATION**

HISTORIC NAME	Union Block
COMMON NAME	I. W. Carey Electric and Plumbing
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; gap between buildings at south end; building constructed to front sidewalk and lot lines; similar in character and materials to building to north

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0887-889.jpg

DIGITAL PHOTO ID2



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Replacement door; mansard roof above storefront

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Antioch Schwinn Cyclery
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; lot slopes slightly to south; alley to north of building; mature tree in front of building

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0890.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Canvas awning (historically appropriate); wood verticals over bulkhead

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Village Stitchery
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; gap between buildings at north end; building constructed to front sidewalk and lot lines; front sidewalks; parallel parking at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0891.jpg

DIGITAL PHOTO ID2	
-------------------	--

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Replacement plate glass windows; replacement front door; replacement door to 2nd story; replacement transom over 2nd story entrance

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	J. J. Blinkers
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**

Building contained the office of Dr. H.F. Beebe, the local health officer during the 1919 flu pandemic, as well as Strang Funeral Home in the 1910s. Historic photographs of building are included (ANTIOCH, ILLINOIS: A PICTORIAL HISTORY, p. 56, 147).

**LANDSCAPE**

Midblock on west side of commercial street; lot slopes to south; front sidewalk; alley on south side; small park/green space on north side; mature tree and lamp post in front

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main089 2-896.jpg

<b>DIGITAL PHOTO ID2</b>	
--------------------------	--

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Entire storefront has been reconfigured with non-historic replacement materials including wood vertical board signboard, bulkhead, transom, and surround, shortened plate glass display windows; and aluminum entry door

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Elite Embroidery
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0893.jpg

DIGITAL PHOTO ID2



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text" value="Queen Anne"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1900"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Metal; stone"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Metal; stone"/>	WINDOW TYPE	<input type="text" value="double hung; fixed"/>
		WINDOW CONFIG	<input type="text" value="1/1; 1 light small display"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


All non-historic replacement materials including entry doors, artificial stone cladding and downsized display windows, cedar shake canopy and back lit signage and wall sconces

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	Village Pub
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front; gap between buildings at south end

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0897-899.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	JENNIFER KENNY
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Replacement front doors; vinyl material on frieze above storefronts; replacement windows

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; small park/greenspace to south; mature tree at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0900.jpg

**DIGITAL PHOTO ID2**



**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Both storefronts have been reconfigured with non-historic materials including wood vertical board panels over signboard and bulkhead; downsized display windows, and replacement entry doors

**HISTORIC INFORMATION**

HISTORIC NAME	Central Bldg.
COMMON NAME	Katie's Country Cottage/ImpressionsCount
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

Partial photograph of building on page 134 of ANTIOCH, ILLINOIS: A PICTORIAL HISTORY.

**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front; gap between buildings at both ends

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0901-905.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT  
ALTERATIONS**

See continuation sheet.

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Fields Building
<b>COMMON NAME</b>	Infini-Tea/Decano Creations/Nail Salon
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**

Historic photograph of building (c. 1945) in the postcard archives of the Lake County Regional Museum. The building was damaged by a fire on November 2, 1950 (from ANTIOCH, ILLINOIS: A PICTORIAL HISTORY, p. 32)

**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; mature tree and lamp post in front

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0902-906.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 902-906

STREET Main

## ADDITIONAL PHOTOS OR INFORMATION

### *Storefront Alterations*

Replacement windows in center and south storefronts; replacement doors in all (configuration has not been altered); Wood sign above north end storefront; lighted sign and paper sign w/ floodlights for center and south storefronts mounted on wood backing; stone veneer below display windows





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Storefronts for 909 and 911 have been completely reconfigured with non-historic wood vertical board; 2nd floor entry door between 909 and 911 storefronts has been infilled with an ATM machine.

**HISTORIC INFORMATION**

HISTORIC NAME	Sibley Block
COMMON NAME	Antioch Music
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front; gab between buildings at north end

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0909-911.jpg

**DIGITAL PHOTO ID2**



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1890"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Brick"/>
WALL MATERIAL (current)	<input type="text" value="Stucco"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Unknown"/>	WINDOW MATERIAL	<input type="text" value="Aluminum"/>
WALL MATERIAL 2 (original)	<input type="text" value="Brick"/>	WINDOW TYPE	<input type="text" value="double hung/fixe"/>
		WINDOW CONFIG	<input type="text" value="1/1; plate glass"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Replacement doors and windows; wood surrounds and bulls eye blocks have been added

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Williams Brother's Department Store
<b>COMMON NAME</b>	Antiques
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**

Appears to be Williams Brother's Department Store, but completely altered. Historic photographs of the building are on page 135 of ANTIOCH, ILLINOIS: A PICTORIAL HISTORY. Interior still contains iron posts.

**LANDSCAPE**

Midblock on west side of commercial street; brick front sidewalk; mature trees at front; alley on south side

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0910.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 910

STREET Main

## ADDITIONAL PHOTOS OR INFORMATION

### *Alterations*

Front façade has been completely altered--stucco cladding; replacement windows (appear to be in downsized openings) with replacement surrounds; decoration at cornice; center sign (removed) with three hanging lights; segmental arch windows on side bricked in; 2 story rear brick addition (historic); large 1 story frame garage addition





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Replacement Aluminum windows and door; altered configuration

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Hair Design Unltd.
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

Historic photograph of building on p. 127 of ANTIOCH, ILLINOIS: A PICTORIAL HISTORY.

**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; mature tree and lamp post in front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0912.jpg

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Storefront has been completely reconfigured with non-historic materials

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0913.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

See continuation sheet.

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Las Vegas Restaurant
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**

According to "Antioch Illinois, Revisited" (newspaper supplement dated March, 1988), the north building was originally the Brook State Bank Building, built c. 1900 after the Bank's first building was damaged by fire (photograph included, p. 14).

**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; lamp posts at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0914.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 914

STREET Main

## ADDITIONAL PHOTOS OR INFORMATION

### *Alterations*

Facades of both buildings have been completely altered---stucco cladding, Greek frieze and round, fluted columns at corners; replacement windows on both buildings in downsized openings; replacement windows on 2nd floor of north side in downsized openings; rear stucco entrance addition on north building with pedimented entry porch; metal spiral rear staircase; replacement windows in enlarged openings on south elevation of north building at rear; 3 story frame rear addition at what was originally the south building; first story windows on north side bricked in

### *Storefront Alterations*

Storefronts on both buildings have been completely altered (configuration and materials)----stucco cladding; Greek key frieze above storefronts; metal plate glass windows and doors; projecting sections above windows and doors (almost like permanent awnings); globe lights; lighted/neon sign (c. 1955)





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL INDR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade"/>
INTEGRITY	<input type="text" value="not altered"/>	REASON for SIGNIFICANCE	<input type="text" value="Only intact section of Sibley Block, with original 2nd story polygonal bay and storefront."/>
STOREFRONT INTEGRITY	<input type="text" value="Minor alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1904"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="Date block"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Common brick"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Common brick"/>	WINDOW TYPE	<input type="text" value="double hung/fixed"/>
		WINDOW CONFIG	<input type="text" value="1/1; single light"/>

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**STOREFRONT FEATURES**




**STOREFRONT ALTERATIONS**


Transom above display windows boarded up

**HISTORIC INFORMATION**

HISTORIC NAME	Sibley Block
COMMON NAME	Antioch Flooring
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**




**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0917.jpg

**DIGITAL PHOTO ID2**



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Storefront has been completely refigured and refaced with artificial stone

**HISTORIC INFORMATION**

HISTORIC NAME	Sibley Block
COMMON NAME	Innovative Ideas
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0919.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Entire storefront has been reconfigured with replacement materials including plate glass display windows, artificial stone cladding at bulkhead, and wood vertical board at signboard level

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Rose of Sharon Boutique
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Lake; building constructed to front sidewalk and lot lines; parallel parking at front; trees along sidewalk; rear asphalt parking lot

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	images\main0921-923.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="One Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1950s"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Stone veneer"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Concrete - block"/>	WINDOW MATERIAL	<input type="text" value="Aluminum"/>
WALL MATERIAL (original)	<input type="text" value="Stone veneer"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Concrete - block"/>	WINDOW TYPE	<input type="text" value="display"/>
		WINDOW CONFIG	<input type="text" value="single light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Cloth awning over entry; replacement door in downsized opening; wood sign

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	At the Green Bench
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on west side of residential street; front sidewalk; mature tree in front of building

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0924.jpg

<b>DIGITAL PHOTO ID2</b>	
--------------------------	--

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT  
ALTERATIONS**


Wood vertical cladding over bulkhead

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	The Bath Works
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC  
INFO**



**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Park; building constructed to front sidewalk and lot lines; parallel parking at front

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0925.jpg

DIGITAL PHOTO ID2	
-------------------	--

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT  
ALTERATIONS**


replacement windows and door; replacement 2nd story entry door; lighted sign above storefront

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	The Barker Shop
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>



**HISTORIC  
INFO**



**LANDSCAPE**

Midblock on west side of residential street; south party wall with 924 Main Street; front sidewalks; parking lot on north side; mature tree in front of building

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\main0926-928.jpg"/>

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1925"/>	ROOF TYPE	<input type="text" value="Flat/parapet"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="plate glass"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung; display"/>
		WINDOW CONFIG	<input type="text" value="5/1; 1/1; 1 light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Entire storefront has been reconfigured with non-historic materials including wood vertical board siding, flush, enlarged display window, and flush aluminum entry doors; signboard extends across alley at south to building next door; backlit signage

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Sports Center
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Park; building constructed to front sidewalk and lot lines; parallel parking at front; gap between buildings on south façade

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0927.jpg

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**

Entire storefront has been reconfigured with non-historic materials including wood vertical board siding, flush display windows that angle into entry; removed 2nd floor entry; signboard extends across alley at south to building next door; backlit signage

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	State Bank of Antioch
<b>COMMON NAME</b>	BJ's Fashions for Men
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**

Building housed the State Bank of Antioch before 934 was constructed (from "Antioch Illinois, Revisited," March, 1988, p. 9--1903 photo included). Photograph of building (appears to be 1950s) is on page 51 of ANTIOCH, ILLINOIS: A PICTORIAL HISTORY.

**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Park; building constructed to front sidewalk and lot lines; parallel parking at front; gap between buildings on both façade

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0931.jpg

<b>DIGITAL PHOTO ID2</b>	
--------------------------	--

**SURVEY INFORMATION**

<b>PREPARER</b>	JENNIFER KENNY
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Bank"/>
INTEGRITY	<input type="text" value="Minor alterations and/or additions"/>	REASON for SIGNIFICANCE	<input type="text" value="Impressive Temple Front building with stone front, triangular pediment, and classical detailing."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Temple Front"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1926"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Brick"/>
WALL MATERIAL (current)	<input type="text" value="Stone"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Metal"/>
WALL MATERIAL (original)	<input type="text" value="Stone"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Brick"/>	WINDOW TYPE	<input type="text" value="fixed"/>
		WINDOW CONFIG	<input type="text" value="Multi-light"/>

SIGNIFICANT FEATURES

ALTERATIONS


STOREFRONT FEATURES



**STOREFRONT ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	State Bank of Antioch
<b>COMMON NAME</b>	The Vault Restaurant
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**

Photograph of bank under construction is located on page 40 of ANTIPOCH, ILLINOIS: A PICTORIAL HISTORY. According to "Antioch Illinois, Revisited," the building was constructed after a 1926 merger between the Brook Bank and State Bank (p. 14).

**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; parking lots on north and south sides; mature trees

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0934.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 934

STREET Main St

## ADDITIONAL PHOTOS OR INFORMATION

### *Alterations*

cloth awning over front entry; replacement door; replacement metal windows on lower sections of round arch windows; replacement window at east end of north elevation in downsized opening; metal and glass enclosed entry on south elevation; 1 story frame shed addition on north elevation; original engraving of "State Bank of Antioch" in frieze under center pediment on front façade partially filled in





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="One Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1910"/>	ROOF TYPE	<input type="text" value="Parapet/flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="plate glass"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="display"/>
		WINDOW CONFIG	<input type="text"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Entire storefront has been reconfigured with non-historic materials including flush plate glass windows, metal cladding, aluminum recessed entry door at side and angled display window

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Sleepwatchers
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Park; building constructed to front sidewalk and lot lines; parallel parking at front; gap between buildings on north façade

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0935.jpg

DIGITAL PHOTO ID2



**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Entire storefront has been reconfigured from a garage to a storefront with non-historic materials including artificial stone cladding, plate glass windows, and glass tile frieze

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Travel by Design
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Park; building constructed to front sidewalk and lot lines; back of building fronts on Skidmore

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0939.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Deeply recessed paired aluminum entry doors (not historic) at side with three bays of display windows

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Flo's Family Hair Care
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on east side of busy commercial highway between Orchard and Park building constructed to front sidewalk and lot lines; parking lot to south (located at NE corner of Park and Main)

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0945.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Storefronts completely reconfigured, with replacement windows, round arch recessed entry for storefront and 2nd story; brick is painted

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; party wall with buildings north and south

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0948-950.jpg

**DIGITAL PHOTO ID2**



**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


wood shingle mansard roof over store front; wood side above mansard; vertical wood paneling below display windows; cloth retractable awning above storefront; replacement door on 2nd floor entry

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Chinn Building
<b>COMMON NAME</b>	Sacred Earth
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; gravel alley on north; party wall on south

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main095 2-954.jpg

<b>DIGITAL PHOTO ID2</b>	
--------------------------	--

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Rear garage and shed roof additions; another historic building in there somewhere?

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	Antioch Floral
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC INFO**



**LANDSCAPE**

On southeast corner of Main and Park Street; mixed uses on block; asphalt parking lot surrounding building; concrete knee wall at south property line

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0959.jpg

DIGITAL PHOTO ID2	
-------------------	--

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	Polson Natural Food
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

Appears to have originally been a car dealership--garage openings on north elevation have been filled in

**LANDSCAPE**

Midblock on west side of commercial street; front sidewalk; gravel alley to south;

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	\\images\main0960.jpg
<b>DIGITAL PHOTO ID2</b>	<input type="text"/>

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATESOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

sign says future home of Lakes Region Historical Society

**LANDSCAPE**

Midblock on east side of mixed use, busy highway between Park and Ida; mature tree at front; alley at north side

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\main0965.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	<input type="text" value="JENNIFER KENNY"/>
PREPARER ORGANIZATION	<input type="text" value="GRANACKI HISTORIC CONSULTANTS"/>
SURVEYDATE	<input type="text" value="11/1/1995"/>
SURVEYAREA	<input type="text" value="DOWNTOWN ANTIOCH"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	Dairy Queen
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of residential street; front sidewalk; parking lots on south and north sides; freestanding sign in south parking lot

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	\images\main0966.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Freestanding"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1.5"/>
BEGINYEAR	<input type="text" value="c. 1930"/>	ROOF TYPE	<input type="text" value="Mansard"/>
OTHER YEAR	<input type="text" value="c. 1975"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Parged"/>
WALL MATERIAL (current)	<input type="text" value="Stucco"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Metal"/>
WALL MATERIAL (original)	<input type="text" value="Unknown"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="Fixed/"/>
		WINDOW CONFIG	<input type="text" value="Single light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	Caldwell Bankers
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

northwest corner of Wilton and Main;  
front sidewalk; front parking lot; rear  
parking lot

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	\\images\main0974.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Recreation and Culture - museum"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Religion - religious facility"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Although there have been multiple alterations, the church building is historically significant."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Church - Greek Revival"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1863"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Plaque"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="vinyl"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="snap-in muntins"/>
SIGNIFICANT FEATURES	<input type="text" value="Front gable roof with cornice return and broad eaves; corner pilasters; wide frieze board; tall window openings with simple classical surrounds; flat pediment over restored paired front doors; central bell tower with vent"/>		
ALTERATIONS	<input type="text" value="Replacement windows in original openings; wood steps that wrap around the front with disabled access ramp; truncated bell tower; one story rear, frame addition (1920s - historic) with replacement windows (not historic)"/>		
STOREFRONT FEATURES	<input type="text"/>		



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	The Meeting House
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of mixed use, busy highway between Park and Ida; concrete steps at curb with pipe rail; power pole at front; asphalt parking at rear; building on slight rise

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	\images\main0977.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	JENNIFER KENNY
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/1/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	Antioch Fine Arts Foundation Art Gallery
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC INFO**

**LANDSCAPE**

At northeast corner of Ida and Main; on mixed use busy highway; mature trees; power pole at front; rear asphalt parking lot and driveway; split rail fencing at front

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	\\images\main0983.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/1/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

"William E. Brook Memorial Wetland Sanctuary and Entertainment Center" Dedicated September 9, 2000"

**LANDSCAPE**

Midblock on west side of Mixed Use street; front lawn which rises at north and south ends; plantings around stage; parking lots to rear, north, and south

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>

**DIGITAL  
PHOTO ID**

\\images\skidmor  
e0904.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/2/2005
SURVEYAREA	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

World War II memorial north of pump house "Dedicated to William C. Thieman October 31, army 1962)---tank on concrete base (U.S. Army 13E861)

**LANDSCAPE**

Midblock on west side of Commercial block; front sidewalk; wide driveway to three-car garage;

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\images\toft.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text" value="GRANACKI HISTORIC CONSULTANTS"/>
<b>SURVEYDATE</b>	<input type="text" value="11/2/2005"/>
<b>SURVEYAREA</b>	<input type="text" value="DOWNTOWN ANTIOCH"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Tudor Revival"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1930"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Vinyl"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixe"/>
		WINDOW CONFIG	<input type="text" value="1/1; single light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	Hair Studio
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of mixed-use street; front sidewalk; north side alley; Mature trees; house set slightly back from sidewalk

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	\images\victoria0955.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/2/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	Cleaners/Fedele's Shoes
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of mixed use street; front sidewalk; south side parking lot; mature trees; power line poles at front

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	\images\victoria0957.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/2/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - professional"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Bungalow"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text" value="Colonial Revival"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1925"/>	ROOF TYPE	<input type="text" value="Hipped/gable"/>
OTHER YEAR	<input type="text" value="1990s"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block, poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="metal"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung; fixed"/>
		WINDOW CONFIG	<input type="text" value="4/4; 9 light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	Antioch Family Chiropractic
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of Victoria between Lake and Wilton; mixed uses on the block, mostly commercial to north and residential to south; mature trees; front sidewalks; similar setbacks; asphalt parking lot to north side and rear with curb cut at front

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	\\images\ victoria0960.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	JENNIFER KENNY
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/2/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES




**STOREFRONT ALTERATIONS**


Entire storefront has been infilled with matching brick and metal double hung windows

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	Biller Press Commercial Printers
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	



**HISTORIC INFO**



**LANDSCAPE**

Midblock on west side of Victoria between Lake and Wilton; mixed uses on the block, mostly commercial to north and residential to south; asphalt parking pad at front; alley to north; front sidewalks; similar setbacks

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\ victoria0 966.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	JENNIFER KENNY
<b>PREPARER ORGANIZATION</b>	GRANACKI HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/2/2005
<b>SURVEYAREA</b>	DOWNTOWN ANTIOCH

## OTHER SIGNIFICANT PROPERTIES







STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Well-preserved example of Gabled Ell residence."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Gabled Ell"/>	PLAN	<input type="text" value="L"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1895"/>	ROOF TYPE	<input type="text" value="Cross gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Parged"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Front entry"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixe"/>
		WINDOW CONFIG	<input type="text" value="1/1; multi-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on south side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\harden0332.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	<input type="text" value="1/5/2006"/>
SURVEYAREA	<input type="text"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="If not for alterations to porch, this house would be rated architecturally significant."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Italianate"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1875"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\harden0341.jpg"/>

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	<input type="text" value="1/5/2006"/>
SURVEYAREA	<input type="text"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="Building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="Handsome late Tudor Revival residence with asymmetrical gable roof and skintled brick."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Tudor Revival"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1940"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text" value="wood"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Metal"/>
WALL MATERIAL 2 (original)	<input type="text" value="Wood"/>	WINDOW TYPE	<input type="text" value="casement/jalousie"/>
		WINDOW CONFIG	<input type="text" value="3-light; 4-light; 8-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of busy highway; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\\images\main0572.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	<input type="text" value="1/3/2006"/>
<b>SURVEYAREA</b>	<input type="text"/>

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 572

STREET Main

## ADDITIONAL PHOTOS OR INFORMATION

### *Significant Features*

Broad asymmetrical front gable roof; skintled blonde brick exterior; round arch recessed side jerkinhead wing on north elevation; three through-the-cornice gable dormers on south elevation; historic wood casement windows; 1 story three-sided window bay on north elevation with copper hipped roof





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC INFO**

**LANDSCAPE**

Midblock on west side of busy 2-lane highway; front sidewalk; front driveway; similar setbacks; mature trees; chain link fence at rear.

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\images\main0712.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	<input type="text" value="1/3/2006"/>
<b>SURVEYAREA</b>	<input type="text"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="School - Gothic Revival"/>	PLAN	<input type="text" value="T"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1892"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Plaque"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Aluminum"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="single hung/fixe"/>
		WINDOW CONFIG	<input type="text" value="3/6; 3-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Antioch School
<b>COMMON NAME</b>	Lakes Region Historical Museum
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	

**HISTORIC  
INFO**

**LANDSCAPE**

Northeast corner of Main and ; west and south sidewalks; parking lot at north

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0817.jpg

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	
<b>SURVEYDATE</b>	1/3/2006
<b>SURVEYAREA</b>	

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Religion - church-related residence"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Religion - church-related residence"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Excellent example of late Queen Anne style architecture, with rounded corner tower with bellcast roof."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Queen Anne"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1900"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="Front entry"/>
WALL MATERIAL 2 (current)	<input type="text" value="Stone veneer"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	Antioch Methodist Church (parsonage)
COMMON NAME	Antioch United Methodist Church office
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC  
INFO

LANDSCAPE

Midblock on west side of busy highway; house set on rise; front sidewalk; concrete steps front sidewalk to front entry; similar setbacks; mature trees

**PHOTO INFORMATION**

ROLL1	
FRAMES1	
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	\\images\main0842.jpg

DIGITAL PHOTO ID2

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	
SURVEYDATE	1/3/2006
SURVEYAREA	

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 842

STREET Main

## ADDITIONAL PHOTOS OR INFORMATION

### *Significant Features*

Broad front gable roof with lower side gables on north and south sides; round corner tower with belcast roof and wood paneled frieze; front entry porch with square brick columns and brick knee wall; historic 1/1 wood windows w/ rusticated stone lintels and sills





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Religion - religious facility"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Religion - religious facility"/>
INTEGRITY	<input type="text" value="addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Even with large rear addition, this handsome Gothic Revival church retains many of its historic features, including shingled bell tower and projecting shingle gables."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Church - Gothic Revival"/>	PLAN	<input type="text" value="irregular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1901"/>	ROOF TYPE	<input type="text" value="Pyramidal"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Cornerstone"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text" value="Wood - shingle"/>	WINDOW MATERIAL	<input type="text" value="Wood/glass block"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Stained glass"/>
WALL MATERIAL 2 (original)	<input type="text" value="Wood - shingle"/>	WINDOW TYPE	<input type="text" value="Fixed/awning"/>
		WINDOW CONFIG	<input type="text"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Antioch Methodist Church
<b>COMMON NAME</b>	
<b>COST</b>	
<b>ARCHITECT</b>	
<b>ARCHITECT2</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of busy highway; house set on rise, with concrete retaining wall at front sidewalk; north and south side driveways; similar setbacks

**PHOTO INFORMATION**

<b>ROLL1</b>	
<b>FRAMES1</b>	
<b>ROLL2</b>	
<b>FRAMES2</b>	
<b>ROLL3</b>	
<b>FRAMES3</b>	
<b>DIGITAL PHOTO ID</b>	\\images\main0848.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	
<b>SURVEYDATE</b>	1/3/2006
<b>SURVEYAREA</b>	



# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 848

STREET Main

## ADDITIONAL PHOTOS OR INFORMATION

### *Significant Features*

Pyramidal roof; square corner bell tower with steeply pitched pyramidal roof with flared ends and paired brackets; top section of tower features wood shingles and pointed arch openings; lower front and south side gables with projecting gable walls with wood shingle cladding and small brackets; three stained glass pointed arch windows below these projecting gable walls; pointed arch stained glass windows on north and south elevations; pointed arch front entry in bell tower with stained glass transom



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="Unusual steeply pitched jerkinhead roof and intact porch distinguish this former residence."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Queen Anne - Free Classic"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1.5"/>
BEGINYEAR	<input type="text" value="c. 1900"/>	ROOF TYPE	<input type="text" value="Jerkinhead"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixd"/>
		WINDOW CONFIG	<input type="text" value="1/1; leaded glass"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of busy highway; front sidewalk; side driveway to rear parking; similar setbacks

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>

**DIGITAL  
PHOTO ID**

\images\main101  
3.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	Lara Ramsey
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	1/4/2005
<b>SURVEYAREA</b>	<input type="text"/>

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 1013

STREET Main St

## ADDITIONAL PHOTOS OR INFORMATION

### *Significant Features*

Steeply pitched cross jerkinhead roof w/ cornice returns; full width front porch w/ hip roof, grouped rounded wood columns on stone piers, and simple wood railing; 1st story, 3-sided window bay on north elevation with leaded glass fixed window on front wall of bay; historic double hung windows with classical lintels





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="Handsome Italianate with ornate detailing under eaves."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Italianate"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1875"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front-enclosed"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="glass brick"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="2/2"/>

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**STOREFRONT FEATURES**

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of busy highway; front sidewalk; side driveway; similar setbacks

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\\images\main1025.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	<input type="text" value="1/5/2006"/>
<b>SURVEYAREA</b>	<input type="text"/>



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="If not for alterations, this would be rated significant for architecture."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Italianate"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1875"/>	ROOF TYPE	<input type="text" value="Pyramidal"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



STOREFRONT  
ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

HISTORIC  
INFO

LANDSCAPE

PHOTO INFORMATION

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\main1028.jpg"/>

DIGITAL PHOTO ID2

SURVEY INFORMATION

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	<input type="text" value="1/4/2006"/>
SURVEYAREA	<input type="text"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Excellent example of Queen Anne residential architecture, with multiple bays and varied wall materials."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Queen Anne"/>	PLAN	<input type="text" value="irregular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="c. 1885"/>	ROOF TYPE	<input type="text" value="Gable on hip"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Front entry"/>
WALL MATERIAL 2 (current)	<input type="text" value="Wood - shingle"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Wood - shingle"/>	WINDOW TYPE	<input type="text" value="double hung/fixd"/>
		WINDOW CONFIG	<input type="text" value="1/1; single light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>

**DIGITAL  
PHOTO ID**

\\images\victoria0  
998.jpg

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	1/4/2005
SURVEYAREA	<input type="text"/>



# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 998

STREET Victoria

## ADDITIONAL PHOTOS OR INFORMATION

### *Significant Features*

Steeply pitched gable on hip roof with overhanging eaves; front and south side 2 story square bays with gable roofs; recessed corner porch with turned columns and spindlework frieze; offset northeast corner window bay above porch; historic double hung and fixed wood windows; varied wall materials under gables and on northeast corner 2<sup>nd</sup> story bay



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="Well-preserved example of Craftsman Bungalow."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Craftsman Bungalow"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1925"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Glass block"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/casement"/>
		WINDOW CONFIG	<input type="text" value="3/1; 4/1; 3-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\images\victoria0999.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	<input type="text" value="1/3/2006"/>
SURVEYAREA	<input type="text"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="not altered"/>	REASON for SIGNIFICANCE	<input type="text" value="Excellent example of Craftsman Bungalow, with broad, open front porch with battered columns."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Craftsman Bungalow"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1925"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/casement"/>
		WINDOW CONFIG	<input type="text" value="3/1; 4/1; 3-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\\images\victoria1003.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	<input type="text" value="1/3/2006"/>
<b>SURVEYAREA</b>	<input type="text"/>



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATESOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\ victoria1 014.jpg"/>

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	<input type="text" value="1/4/2005"/>
SURVEYAREA	<input type="text"/>

# Village of ANTIOCH

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 1014

STREET Victoria

## ADDITIONAL PHOTOS OR INFORMATION

### *Significant Features*

Multiple rooflines and irregular massing; large front tower at front façade with unusual polygonal front gable roof, 1st story cutaway corners w/ hanging pendants and 2nd story polygonal window bay; multiple wall materials; historic double hung, awning, and fixed windows with molded hoods and corner bull's eye blocks





STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="not altered"/>	REASON for SIGNIFICANCE	<input type="text" value="Good example of Craftsman Bungalow, with intact front porch with battered brick columns and shingled knee wall."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Craftsman Bungalow"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="c. 1920"/>	ROOF TYPE	<input type="text" value="Side gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Wood - shingle"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood - shingle"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/awning"/>
		WINDOW CONFIG	<input type="text" value="12/1; 6/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of residential street; front sidewalk; shared side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\\images\victoria1023.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	<input type="text" value="1/3/2006"/>
<b>SURVEYAREA</b>	<input type="text"/>



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Good example of 1870s Italianate residence, with shallow pyramidal roof and scrolled brackets under eaves."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Italianate"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1875"/>	ROOF TYPE	<input type="text" value="Pyramidal"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="1/1"/>
SIGNIFICANT FEATURES	<input type="text" value="Pyramidal roof with scrolled brackets under eaves and wide wood frieze; three-sided window bay under porch on front façade"/>		
ALTERATIONS	<input type="text" value="Alterations to front porch (columns and railing replaced); construction work/bracing above porch"/>		
STOREFRONT FEATURES	<input type="text"/>		

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\victoria1026.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	<input type="text" value="1/4/2005"/>
SURVEYAREA	<input type="text"/>



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Queen Anne"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="c. 1905"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Concrete - block"/>	PORCH	<input type="text" value="Front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Concrete - block"/>	WINDOW MATERIAL	<input type="text" value="Metal"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixed/jalousie"/>
		WINDOW CONFIG	<input type="text" value="1/1; 1 story"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES



**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

ROLL1	<input type="text"/>
FRAMES1	<input type="text"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="\\images\ victoria1 037.jpg"/>

**DIGITAL  
PHOTO ID2**

**SURVEY INFORMATION**

PREPARER	<input type="text" value="Lara Ramsey"/>
PREPARER ORGANIZATION	<input type="text"/>
SURVEYDATE	<input type="text" value="1/3/2006"/>
SURVEYAREA	<input type="text"/>

STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="If not for siding, this would be a significant rated Craftsman Bungalow."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Craftsman Bungalow"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1.5"/>
BEGINYEAR	<input type="text" value="c. 1920"/>	ROOF TYPE	<input type="text" value="Side gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Aluminum"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="9/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**

<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\images\victoria1055.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	<input type="text" value="1/3/2006"/>
<b>SURVEYAREA</b>	<input type="text"/>



STREET #

DIRECTION

STREET

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Intact example of T-form residence."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		
	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="T-Form"/>	PLAN	<input type="text" value="T"/>
DETAILS	<input type="text" value="Queen Anne"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1890"/>	ROOF TYPE	<input type="text" value="Cross"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Parged/stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Front entry"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

**STOREFRONT  
ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC  
INFO**

**LANDSCAPE**

Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**PHOTO INFORMATION**


<b>ROLL1</b>	<input type="text"/>
<b>FRAMES1</b>	<input type="text"/>
<b>ROLL2</b>	<input type="text"/>
<b>FRAMES2</b>	<input type="text"/>
<b>ROLL3</b>	<input type="text"/>
<b>FRAMES3</b>	<input type="text"/>
<b>DIGITAL PHOTO ID</b>	<input type="text" value="\\images\ victoria1 060.jpg"/>

**DIGITAL PHOTO ID2**

**SURVEY INFORMATION**

<b>PREPARER</b>	<input type="text" value="Lara Ramsey"/>
<b>PREPARER ORGANIZATION</b>	<input type="text"/>
<b>SURVEYDATE</b>	<input type="text" value="1/3/2006"/>
<b>SURVEYAREA</b>	<input type="text"/>





## ANTIOCH HISTORIC SURVEY: EVALUATION CRITERIA

All principal buildings in the area surveyed were evaluated for local architectural significance using the criteria for architectural significance outlined below. An "S" indicates that a building would be eligible for listing as an individual local landmark. A "C" indicates that it would be a contributing building in a locally designated historic district, generally more than 50 years old. Under certain circumstances, a building less than 50 years of age could be ranked "S," provided that the building is of exceptional architectural or historical significance. An "NC" would be a building that does not contribute to the time period of significance for a local historic district.


Integrity, that is, the degree of original design and historic material remaining in place, was factored into the evaluation. No building was considered locally significant if it had more than minor alterations. Similarly, buildings that might otherwise be considered contributing because of age and historic style, but that have been greatly altered, were ranked as non-contributing. Buildings were evaluated primarily for their architectural significance, with historical significance, known in only a few cases, being a secondary consideration. It is possible that a building could be elevated to a locally significant ranking and thus considered for individual local landmark designation by the Historic Preservation Commission if additional historic research identifies an association with important historical figures or events. For some buildings whose significant historic features have been concealed or altered, they might also be re-ranked as locally significant if unsympathetic alterations are removed and significant historic features restored.

Next, all principal and secondary structures on a property were analyzed for potential National Register listing. A "Y" (Yes) indicates that the surveyed building likely would be a good candidate for individual listing on the National Register (or, in some cases, has already been listed on the National Register). An "N" (No) indicates that it would not. "Criteria" refers to the National Register criteria that were considered. Only criterion "C," architectural significance, was used in evaluating potential National Register eligibility. Criteria "A" and "B," which refer to historical events and persons, were not considered. For the question of contributing to a National Register District, a "C" building would be a good contributing building in a National Register historic district. An "NC" building would not. Some buildings are already listed on the National Register or in a National Register district, and they are marked "NR" under "listed on existing survey."

The other notations under "listed on existing survey" include IHSS, which indicates the building was included in the Illinois Historic Structures Survey, completed by the State Historic Preservation Office in the early 1970s.

Architectural integrity is evaluated by assessing what alterations to the original historic structure have occurred. Structures were considered unaltered if all or almost all of their historic features and materials were in place. Minor alterations were those considered by the field surveyor to be reversible. Generally, aluminum, vinyl, or other siding installed over original wood clapboard siding is considered a reversible alteration. Major alterations include irreversible changes and additions. These include porches and other architectural detailing that have been completely removed and for which there is no actual physical





evidence or photo documentation to accurately reproduce them; window changes in which the original window opening size has been altered and there is no evidence of the original sash configuration and material; and large unsympathetic additions, visible from the street, that compromise the historic character of a house.

## **NATIONAL REGISTER RATINGS**

### **A. INDIVIDUAL LISTING (Y)**

- Must be a site, building, structure, or object that is at least 50 years old (unless it has achieved exceptional significance) and meets one of the following criteria: (a) be associated with events that have made a significant contribution to the broad patterns of our history; (b) be associated with the lives of persons significant in our past; (c) be architecturally significant, that is, embody the distinctive characteristics of a type, period, or method of construction, or represent the work of a master, or possess high artistic values. It must also possess integrity of location, design, setting, materials, workmanship, feeling, and association from the date of construction or period of significance.

### **B. CONTRIBUTING TO A HISTORIC DISTRICT (C)**

- Age. Must have been built or standing during the period of historic significance or be at least 50 years old or older (built before 1956).
- Integrity. Any building that possesses enough integrity to still be identified with the period of historic significance.


### **C. NON-CONTRIBUTING (NC)**

- Age. Any building or secondary structure built after the period of significance or less than 50 years old (built in 1957 or later).
- Integrity. Any structure that has been so completely altered after the period of significance that it is no longer recognizable as historic.

## **LOCAL SIGNIFICANCE RATINGS\***

### **A. SIGNIFICANT (S)**

- Age. There is no age limit, although if it is less than 50 years old (built after 1956), it must be of exceptional importance.



- **Architectural Merit.** Must possess architectural distinction in one of the following areas: embodies the distinguishing characteristics of an architectural and/or landscape style; is identified as the work of a master builder, designer, architect, or landscape architect; has elements of design, detailing, materials, or craftsmanship that are significant; has design elements that make it structurally or architecturally innovative; is a fine example of a utilitarian structure with a high level of integrity. Any structure ranked significant automatically contributes to the character of a historic district.
- **Integrity.** Must have a high degree of integrity: most architectural detailing in place, no historic materials or details covered up, no modern siding materials, no unsympathetic and/or overpowering additions; only minor porch alterations permitted. In some rare cases, where a particular structure is one of the few examples of a particular style, more leniency in integrity was permitted.

#### B. CONTRIBUTING TO A HISTORIC DISTRICT (C)

- **Age.** Must be at least 50 years old (built before 1954).
- **Architectural Merit.** May fall into one of two groups: (a) Does not necessarily possess individual distinction, but is a historic building (over 50 years old) with the characteristic stylistic design and details of its period; or (b) possesses the architectural distinction of a significant structure but has been altered. If the alterations are reversed (for example, siding is removed or architectural detail is restored based on remaining physical evidence), it may be elevated to significant.
- **Integrity.** May have a high degree of integrity, but be of a common design with no particular architectural distinction to set it apart from others of its type. May have moderate integrity: if it has been altered, it must be in some ways that can be reversed. Must possess at least one of the following: original wall treatment, original windows, interesting architectural detail, readily recognizable and distinctive historic massing.

#### C. NON-CONTRIBUTING (NC)

- **Age.** Most buildings less than 50 years old (built in 1957 or later).
- **Integrity.** Any building at least 50 years old whose integrity is so poor that most historic materials and details are missing or completely covered up or any building over 50 years old that has unsympathetic alterations that greatly compromise its historic character. Poor integrity was present if all of these factors were missing: original shape, original wood siding, original windows (especially if window openings were also changed), original architectural detail and trim.

\*The local evaluation criteria outlined here are based on local landmark designation criteria found in the historic preservation ordinances of several northeastern Illinois communities.

